

DESIGN & CONSTRUCTION GROUP THE GOVERNOR NELSON A. ROCKEFELLER EMPIRE STATE PLAZA ALBANY, NY 12242

ADDENDUM NO. 3 TO PROJECT NO. 47295

CONSTRUCTION WORK
PROVIDE MASONRY REPAIR, PHASE 2
STATE ARMORY
2366 5TH AVENUE
NEW YORK, NY

April 23, 2024

NOTE: This Addendum forms a part of the Contract Documents. Insert it in the Project Manual. Acknowledge receipt of this Addendum in the space provided on the Bid Form.

DRAWINGS

- 1. Revised Drawings
 - a. Drawing Nos. G-005, G-006 and A-578, noted "ADDENDUM # 3 4/16/2024" accompany this Addendum and supersede the same numbered originally issued drawings.

END OF ADDENDUM

Brady Sherlock, P.E. Director, Division of Design Design & Construction

RESTORATION SUMMARY

ITEM	SPECIFICATION	DETAIL CODE	DESCRIPTION	UNIT	DWG
Α	REFERENCE		REMOVAL		
01	024119	DEM 01	EPDM REMOVAL: MASONRY WALLS, PARAPETS & COPINGS	SF	AD-501
В			CLEANING		
01	040123	CLN 01	CLEANING - BRICK MASONRY	SF	A-504
02	040123	CLN 02	CLEANING - GRANITE UNITS	SF	A-504
03	040123	CLN 03	CLEANING - SANDSTONE UNITS	SF	A-505
04	040123	CLN 04	CLEANING - TERRA COTTA COPING AND PANELS	SF	A-505
05	040123	CLN 06	POST CONSTRUCTION POWER WASH	SF	A-507
С			CONCRETE		
01	033001	CON 03	CONCRETE FOUNDATION RESTORATION BELOW PIER	EA	A-512
01	000001	0011 03	CONCRETE T GONDATION REGTORATION BELOW FIELD	LA	7,012
D			MASONRY		
01	042129	COP 01	TERRA COTTA COPING UNIT REPLACEMENT	EA	A-513 TO A-5
02	042113	COR 02	CORNER RECONSTRUCTION: BRICK MASONRY AT SOUTHWEST CORNER OF ADMINISTRATION BUILDING	LF	A-522
03	042113	MAS 01	CRACKED BRICK REPAIR	LF	A-558
04	042113	MAS 02	INDIVIDUAL BRICK REPLACEMENT	EA	A-559
05	042113	MAS 03	SPALLED BRICK REPLACEMENT	SF	A-559
06	042113	MAS 04	BRICK MASONRY SLOPE SILL RESTORATION	EA	A-560
07	042113	MAS 05	BRICK WALL RESTORATION AT SUNKEN ENTRANCE	SF	A-561
80	042113	MAS 06	REPLACE BRICK BELT COURSE SPECIAL SHAPE	LF	A-562
09	042113	MAS 07	CRACKED BRICK REPAIR AND CAP FLASHING	LF	A-562
10	042113	PIR 01	MASONRY PIER RECONSTRUCTION AT ADMINISTRATION BUILDING PEROINTING: PRICK MORTAR JOINTS	EA	A-564 TO A-5
11	040513	PNT 01	REPOINTING: BRICK MORTAR JOINTS	SF	A-566
12 13	040513 040513	PNT 02 PNT 03	REPOINT SANDSTONE MORTAR JOINTS REPOINT GRANITE MORTAR JOINTS ADMIN. BUILDING	LF LF	A-567 A-567
14	040513	PNT 03	REPOINT GRANTE MORTAR JOINTS ADMIN. BOILDING REPOINT TERRA COTTA MORTAR JOINTS	LF LF	A-567
15	044301	SIL 01	BLUESTONE SILL REPLACEMENT AT MECHANICAL PENTHOUSE	LF	A-507 A-570
16	044301	SIL 02	BLUESTONE SILL REPLACEMENT AT SLOPED MASONRY	LF	A-570
17	042113	SPN 01	ROOF LEVEL SPANDREL RESTORATION: BRICK MASONRY - ADMIN. BUILDING	LF	A-573
 18	044301	STN 01	SANDSTONE UNIT REPLACEMENT	EA	A-576
19	044301	STN 02	GRANITE UNIT REPLACEMENT	EA	A-577
20	044301	STN 02A	RESET GRANITE UNIT	EA	A-578
21	044301	STN 03	STONE DUTCHMAN: GRANITE	SI	A-579
22	040130	TRC 01	TERRA COTTA SPALL REPAIR	SI	A-581
23	040130	TRC 02	TERRA COTTA CRACK REPAIR	LI	A-582
24	040130	TRC 03	TERRA COTTA DECORATIVE PANEL REPLACEMENT	EA	A-583 TO A-5
25	099623	COA 05	PROVIDE ANTI-GRAFFITI COATING ON GROUND FLOOR AT BRICK MASONRY	SF	N/A
E 01	054200	1.71.04	CITES LINITED DEDI ACEMENT AT ADMINI DI DO DEDICIO DEDED AT ODCUME SI COD	ı.e.	A 507
01	051200 051200	LTL 01	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: BRICK BORDER AT GROUND FLOOR STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: BRICK BORDER AT GROUND FLOOR (NO WINDOW)	LF LF	A-537 A-538
03	051200	LTL 02	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: FLUSHED BRICK BORDER	LF	A-536 A-539
04	051200	LTL 03A	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: 3-OPENINGS BETWEEN BRICK PIERS AT BAY 7	LF	A-540
05	051200	LTL 03B	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: 3-OPENINGS BETWEEN BRICK PIERS AT BAY 6	LF	A-541
06	051200	LTL 04A	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: 3-OPENINGS BETWEEN BRICK PIERS AT BAYS 1 & 4	LF	A-542
07	051200	LTL 04B	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: 3-OPENINGS BETWEEN BRICK PIERS AT BAY 3	LF	A-543
08	051200	LTL 04C	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: 3-OPENINGS BETWEEN BRICK PIERS AT TERRA COTTA UNITS AT BAYS 1 & 4	LF	A-544
09	051200	LTL 04D	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: 3-OPENING BETWEEN BRICK PIERS AT TERRA COTTA UNITS (NO WINDOWS)	LF	A-545
10	051200	LTL 05	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: SINGLE OPENING BETWEEN BRICK PIERS AT BAYS 1, 2, & 5	LF	A-546
11	051200	LTL 06	STEEL LINTELS REPLACEMENT AT ADMIN. BLDG.: BRICK AND GRANITE PANELS	LF	A-547
12	051200	LTL 07	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: BRICK PANEL OVER ENTRANCE	LF	A-548
F			JOINT SEALANTS		
01	079200	JNT 01	JOINT SEALANT REPLACEMENT AT OPENING PERIMETERS AT ADMIN BLDG	LF	A-530 TO A-5
02	079200	JNT 02	WEATHER CAP REPLACEMENT: COPING CROSS-JOINTS	LF	A-532
03	079200	JNT 03	JOINT SEALANT REPLACEMENT: GRANITE-TO-SIDEWALK JOINT	LF	A-532
	079200	LTG 01	LIGHTNING PROTECTION REINSTALLATION	LF	A-536
		PEN 01	SEAL THRU - WALL PENETRATION	EA	A-563
	079200	I LIN OI			
05		1 LIN 01	DOORS WINDOWS & LOUVERS		
05 G		SHM 01	DOORS, WINDOWS & LOUVERS SHEET METAL MOLDING AT WINDOWS	LF	A-568
05 G	079200			LF	A-568
04 05 G 01	079200			LF	A-568
05 G 01	079200		SHEET METAL MOLDING AT WINDOWS	LF EA	A-568 A-508
05 G 01	079200 076000	SHM 01	SHEET METAL MOLDING AT WINDOWS STEEL COATINGS		
05 G 01 H	079200 076000 099101 099101 099101	SHM 01 COA 02 COA 03 GAT 02	SHEET METAL MOLDING AT WINDOWS STEEL COATINGS COAT EXISTING ENTRANCE DOOR	EA LF EA	A-508 A-508 A-525
05 G 01 H 01 02	079200 076000 099101 099101 099101	SHM 01 COA 02 COA 03 GAT 02 GRL 01	SHEET METAL MOLDING AT WINDOWS STEEL COATINGS COAT EXISTING ENTRANCE DOOR COAT EXISTING EXPOSED STEEL REFURBISH & REINSTALL EXISTING IRON FENCE AT RETAINING WALL OF ADMIN. BUILDING REFURBISH & REINSTALL EXISTING WINDOW GRILLE	EA LF EA EA	A-508 A-508 A-525
05 G 01 H 01 02 03 04 05	079200 076000 099101 099101 099101 099101 055000	SHM 01 COA 02 COA 03 GAT 02 GRL 01 GRL 02	SHEET METAL MOLDING AT WINDOWS STEEL COATINGS COAT EXISTING ENTRANCE DOOR COAT EXISTING EXPOSED STEEL REFURBISH & REINSTALL EXISTING IRON FENCE AT RETAINING WALL OF ADMIN. BUILDING REFURBISH & REINSTALL EXISTING WINDOW GRILLE NEW WINDOW GRILLE	EA LF EA	A-508 A-508 A-525
05 G 01 H 01 02 03 04	079200 076000 099101 099101 099101	SHM 01 COA 02 COA 03 GAT 02 GRL 01	SHEET METAL MOLDING AT WINDOWS STEEL COATINGS COAT EXISTING ENTRANCE DOOR COAT EXISTING EXPOSED STEEL REFURBISH & REINSTALL EXISTING IRON FENCE AT RETAINING WALL OF ADMIN. BUILDING REFURBISH & REINSTALL EXISTING WINDOW GRILLE	EA LF EA EA	A-508 A-508 A-525 A-527 TO A-5

ITEM A	SPECIFICATION REFERENCE	DETAIL CODE	DESCRIPTION CLEANING	UNIT	DWG
01	040123	CLN 01	CLEANING - BRICK MASONRY	SF	A-504
02	040123	CLN 05	CLEANING - TERRA COTTA UNITS	SF	A-504
				SF	
03	040123	CLN 06	POST CONSTRUCTION POWER WASH		A-507
04	040123	STR 01	COATING REMOVAL: GRANITE STAIRS AT ENTRANCES & SEAL JOINTS	SF	A-580
_			CONODETE		
B	000404	000104	CONCRETE	01	A 540
01	030131	CON 01	SPALLED CONCRETE REPAIR	SI	A-510
02	030132	CON 02	CRACKED CONCRETE REPAIR	LI	A-511
С			MASONRY		
01	042129	COP 02	TERRA COTTA COPING UNIT REPLACEMENT - DRILL HALL	EA	A-520
02	040130	FLA 01	TERRA COTTA PATCHING COMPOUND FLASHING	LI	A-523
03	042113	MAS 01	CRACKED BRICK REPAIR	LF	A-558
04	042113	MAS 02	INDIVIDUAL BRICK REPLACEMENT	EA	A-559
05	042113	MAS 03	SPALLED BRICK REPLACEMENT	SF	A-559 A-559
				SF	
06	040513	PNT 01	REPOINTING: BRICK MORTAR JOINTS		A-566
07	040513	PNT 04	REPOINTING: TERRA COTTA MORTAR JOINTS O3 O3 O3 O3 O3 O3 O3 O3 O3 O	LF	A-567
08	040130	SIL 03	TERRA COTTA SILL REPAIR. DRILL HALL	EA .	A-571
09	042129	SIL 04	TERRA COTTA SILL REPLACEMENT: BELOW LOUVER	EA	A-571
10	042113	SPN 02	ROOF LEVEL SPANDREL RESTORATION: BRICK MASONRY - DRILL HALL	LF	A-574
11	044301	STN 03	STONE DUTCHMAN: GRANITE	SI	A-579
12	040130	TRC 01	TERRA COTTA SPALL REPAIR	SI	A-581
13	040130	TRC 02	TERRA COTTA CRACK REPAIR	LI	A-582
14	042129	TRC 04	TERRA COTTA UNIT REPLACEMENT - DRILL HALL	EA	A-585 TO A-
15	042129	TRC 05	TERRA COTTA CANOPY RECONSTRUCTION SOUTH	EA	A-589 TO A
16	042129	TRC 06	TERRA COTTA CANOPY RECONSTRUCTION NORTH	EA	A-592 TO A-
17	099623	COA 05	PROVIDE ANTI-GRAFFITI COATING ON GROUND FLOOR AT BRICK MASONRY	SF	N/A
D			LINTELS		
01	051200	LTL 09	STEEL LINTEL REPLACEMENT AT DRILL HALL: GROUND FLOOR	LF	A-550
02	051200	LTL 10	STEEL LINTEL REPLACEMENT AT DRILL HALL: FIRST FLOOR	LF	A-551
03	051200	LTL 11	STEEL LINTEL REPLACEMENT AT DRILL HALL: SECOND FLOOR	LF	A-552
04	051200	LTL 12A	STEEL LINTEL REPLACEMENT AT DRILL HALL: THIRD FLOOR	LF	A-553
05	051200	LTL 12B	STEEL LINTEL REPLACEMENT AT DRILL HALL: THIRD FLOOR AT CORNICE	LF	A-554
06	051200	LTL 13	STEEL BEAM RESTORATION AT DRILL HALL: GARAGE	LF	A-555
07	051200	LTL 14	STEEL BEAM RESTORATION AT DRILL HALL: ENTRANCE ABOVE CANOPY	LF	A-556
80	051200	STL 01	STEEL BEAM REINFORCEMENT AT GARAGE ENTRANCE	LF	A-575
09	051200	STL 02	STEEL BEAM REINFORCEMENT AT TERRA COTTA CANOPY	LF	A-588
E	07000	W.T. 00	JOINT SEALANTS		1.500
01	079200	JNT 02	WEATHER CAP REPLACEMENT: COPING CROSS-JOINTS	LF	A-532
02	079200	JNT 04	JOINT SEALANT REPLACEMENT AT OPENING PERIMETERS AT DRILL HALL	LF	A-533
03	079200	JNT 05	JOINT SEALANT REPLACEMENT: EXPANSION JOINT	LF	A-534
04	079200	JNT 06	JOINT SEALANT REPLACEMENT: GRANITE STAIRS AT ENTRANCES	LF	A-535
05	079200	JNT 07	JOINT SEALANT REPLACEMENT: AT SIDEWALK	LF	A-534
06	079200	PEN 01	SEAL THRU-WALL PENETRATION	EA	A-563
F			DOORS & WINDOWS		
_	081102	DOR 01	DOOR REPLACEMENT (PAIR)	EA	A-523
01	081102	GLA 01	GLAZING REPLACEMENT IN DIOCLETIAN WINDOWS / ARCH	EA EA	A-523 A-526
UZ	000 100	GLA UI	OLAZINO NEFLAGLIVILINI IIN DIOGLETIAN WIINDOWS / ARGI	EA	A-526
G			STEEL COATINGS		
01	099101	COA 01	COATING EXISTING C-CHANNEL	LF	A-508
02	099101	COA 04	COAT EXISTING CANOPY	LF	A-508 A-509
03	055000	GAT 01	STEEL GATE REPLACEMENT	EA	A-509 A-524
			REFURBISH & REINSTALL EXISTING WINDOW GRILLE		
04	099101	GRL 01	WINDOW SECURITY SCREEN REFURBISH COATING & REINSTALLATION	EA	A-527 TO A- A-569
05	099101	SCR 01	CONTROL OF SELECTION OF SELECTIONS OF A SELECTION O	⊢ Δ	Δ-56Q

The noted designation of units are: SF: Square Foot
SI: Square Inch
LF: Linear Foot
LI: Linear Inches
EA: Each

05 099101

RESTORATION CODE ABBREVIATIONS

CLN	- CLEANING	GAT	- GATE	PNT	- POINTING	STR	- STAIRS	
COA	- COATING	GLA	- GLAZING	RAI	- RAILING	TRC	- TERRA COTTA	
CON	- CONCRETE	GRL	- WINDOW GRILLE	SCR	- WINDOW SCREEN			
COP	- COPING	JNT	- JOINT	SHM	- SHEET METAL			
COR	- CORNER	LTL	- LINTEL	SIL	- SILL			
DEM	- DEMOLITION/ REMOVAL	MAS	- MASONRY	SPN	- SPANDREL			
DOR	- DOOR	PEN	- PENETRATION	STL	- STEEL			
FLA	- FLASHING	PIR	- PIER	STN	- STONE			

SCR 01 WINDOW SECURITY SCREEN REFURBISH, COATING, & REINSTALLATION




ALL ALTERNATE ITEMS ARE LISTED ON THE FOLLOWING SHEET.



DESIGN & CONSTRUCTION

CONSULTANT

CERTIFICATE OF AUTHORIZATION #: 0006552



14 WALL ST **NEW YORK, NY**

Environmental Sub-consultants: WATTS Architecture & Engineering Estimate Sub-consultants: Singleton Construction Consultants

ENERGY CODE WRITTEN STATEMENT: TO THE BEST OF THE REGISTERED DESIGN PROFESSIONAL'S KNOWLEDGE, BELIEF, AND
PROFESSIONAL JUDGEMENT, THE DRAWINGS, BEARING MY
PROFESSIONAL SEAL AND SIGNATURE MEET OR EXCEED THE 2020 NEW YORK STATE ENERGY CODE CONSISTING OF THE 2018 INTERNATIONAL ENERGY CONSERVATION CODE, 2016 ASHRAE 90.1.

UNIFORM CODE STATEMENT: TO THE BEST OF THE REGISTERED DESIGN PROFESSIONAL'S KNOWLEDGE, BELIEF AND PROFESSIONAL JUDGEMENT. THESE PLANS AND/ OR SPECIFICATIONS ARE IN COMPLIANCE WITH THE 2020 UNIFORM CODE.

WARNING:

THE ALTERATION OF THIS MATERIAL IN ANY WAY, UNLESS DONE UNDER THE DIRECTION OF A COMPARABLE PROFESSIONAL, I.E. ARCHITECT FOR AN ARCHITECT, ENGINEER FOR AN ENGINEER OR LANDSCAPE ARCHITECT FOR A LANDSCAPE ARCHITECT, IS A VIOLATION OF THE NEW YORK STATE EDUCATION LAW AND/OR REGULATIONS AND IS A CLASS 'A' MISDEMEANOR.



CONSTRUCTION

PROVIDE MASONRY REPAIRS PHASE 2

LOCATION:

STATE ARMORY 2366 5TH AVENUE NEW YORK, NEW YORK

DIVISION OF MILITARY AND NAVAL AFFAIRS

Δ	04/40/0004	100510111 #7
	04/16/2024	ADDENDUM #3
MADIC	02/27/2024	BID DOCUMENTS
MARK	DATE	DESCRIPTION
PROJECT NUMBER:	47295	5 - C
DESIGNED BY:	NK	K/KH
DDAWAL DV	15 (15 (17 (1	VIEW (124 (124 (124 (124 (124 (124 (124 (124

DRAWN BY: AB/HB/MZ/MEK/VY/LY/OG FIELD CHECK: APPROVED:

A-569

EA

RESTORATION SUMMARY

DRAWING NUMBER:

G-005

of 133

ASSU	ASSUMED QUANTITIES - DRILL HALL - SCREEN AND GRILLE ANCHORING ONLY					
ITEM	SPECIFICATION REFERENCE	DETAIL CODE	DESCRIPTION	QTY	UNIT	DWG
Α			MASONRY			
01	042113	MAS 03	SPALLED BRICKS REPLACEMENT	165	SF	A-559

Quantities above are assumed per conditions for unforeseen conditions, including but not limited to, masonry crack/ spall repairs, terra cotta crack/ spall repairs, mortar joint repointing, and terra cotta replacement. After Contractor completes work per detail DEM01, Contractor shall perform Confirmation Surveys to verify Quantities per conditions observed. The Confirmation Survey shall include, but not be limited to, location of condition, type of repair, condition quantity, and photo documentation for review by Director's Representative. 10^{-10}

As mentioned above assumed quantities are ONLY for unforeseen conditions under the EPDM membrane at the Administration Building. These assumed quantities are NOT the total quantities for the project instead for the Contractor to reference for bidding purposes due to the area covered by EPDM.

The assumed quantities listed on this sheet are the sum total of assumed quantities indicated on the elevations, plans, enlarged elevations, and enlarged plans within the contract drawings (ranging from, but not limited to, Sheets A-104 to A-403). The assumed quantities are an addition to the non-assumed quantities indicated on all the plans and elevations within the contract drawings. Any assumed quantity is noted as "assumed"; Contractor shall retrieve the non-assumed quantities using the plans and elevations provided within the contract drawings.

The noted designation of units are: SF: Square Foot SI: Square Inch LF: Linear Foot 03 LI: Linear Inches EA: Each

BID A	LTERNATE #1				
ITEM	SPECIFICATION REFERENCE	DETAIL CODE	DESCRIPTION	UNIT	DWG
Α			REMOVAL		
01	024119	DEM 01	EPDM REMOVAL: MASONRY WALLS, PARAPETS & COPINGS	SF	AD-501
02	024119	DEM 02	CHIMNEY DEMOLITION AND NEW PARAPET COPING	EA	AD-502
03	024119	DEM 03	PARTIAL CHIMNEY DEMOLITION AND NEW TERRA COTTA COPINGS	EA	AD-503
В			CLEANING		
01	040123	CLN 01	CLEANING - BRICK MASONRY	SF	A-504
02	040123	CLN 04	CLEANING - TERRA COTTA COPING AND PANELS	SF	A-505
03	040123	CLN 06	POST CONSTRUCTION POWER WASH	SF	A-507
В			MASONRY		
01	042129	COP 01	TERRA COTTA COPING UNIT REPLACEMENT	EA	A-513 TO A-519
02	042113	COR 01	CORNER RECONSTRUCTION: BRICK MASONRY AT OUTSIDE CORNER	LF	A-521
03	042113	MAS 01	CRACKED BRICK REPAIR	LF	A-558
04	042113	MAS 02	INDIVIDUAL BRICK REPLACEMENT	EA	A-559
05	042113	MAS 03	SPALLED BRICK REPLACEMENT	SF	A-559
06	040513	PNT 01	REPOINTING: BRICK MORTAR JOINTS	SF	A-566
07	040513	PNT 04	REPOINTING TERRA COTTA MORTAR JOINTS	EA	A-567
08	044301	SIL 01	BLUESTONE SILL REPLACEMENT AT MECHANICAL PENTHOUSE	LF	A-570
09	042113	SPN 01	ROOF LEVEL SPANDREL RESTORATION: BRICK MASONRY - ADMIN. BUILDING	LF	A-573
10	040130	TRC 01	TERRA COTTA SPALL REPAIR	SI	A-581
11	040130	TRC 02	TERRA COTTA CRACK REPAIR	LI	A-582
С			STEEL COATINGS		
01	099101	COA 03	COAT EXISTING EXPOSED STEEL	LF	A-508
02	099101	SCR 01	WINDOW SECURITY SCREEN REFURBISH, COATING, & REINSTALL	EA	A-569
D			JOINT SEALANTS		
01	079200	JNT 01	JOINT SEALANT REPLACEMENT AT OPENING PERIMETERS AT ADMIN BLDG	LF	A-530 TO A-532
02	079200	JNT 02	WEATHER CAP REPLACEMENT: COPING CROSS-JOINTS	LF	A-532
03	079200	PEN 01	SEAL THRU - WALL PENETRATION RESTORATION	EA	A-563
E			LINTELS		
01	051200	LTL 02A	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: MECHANICAL PENTHOUSE (NO WINDOWS)	LF	A-539
02	051200	LTL 04B	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: 3-OPENINGS BETWEEN BRICK PIERS AT BAY 3	LF	A-543
03	051200	LTL 05	STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: SINGLE OPENING BETWEEN BRICK PIERS AT BAYS 1, 2, & 5	LF	A-546
	054000	1.71.00	OTEFL LINTEL DEDLA GEMENT AT ADMINI DI DO MAGGNIDV ODENINGO AT MEGUIANIGAL DENTUGUE		A 540

ASSU	MED QUANTIT	IES - ALTERN	IATE #1 ONLY			
ITEM	SPECIFICATION REFERENCE	DETAIL CODE	DESCRIPTION	QTY	UNIT	DWG
Α			MASONRY			·····
01	040130	COP 01	TERRA COTTA COPING UNIT REPLACEMENT - ADMIN BUILDING	10	EA	A-401 TO A-403
02	042113	MAS 03	SPALLED BRICKS REPLACEMENT	53	SF	A-559
03	040130	TRC 01	TERRA COTTA SPALL REPAIR	1,325	SI	A-581
04	040130	TRC 02	TERRA COTTA CRACK REPAIR	1,270	LI	A-582

LTL 08 STEEL LINTEL REPLACEMENT AT ADMIN. BLDG.: MASONRY OPENINGS AT MECHANICAL PENTHOUSE

DETAIL CODE/ PREFIX	DIMENSIONS/EXTENTS	REQ'D APPROVAL	BUILDING
CLN	3' x 3' surface area	YES	AB & DH
COA	18" long x full depth of steel member 2' x 2' area at Door	YES	AB & DH
CON	as directed by Architect	YES	DH
СОР	whole unit	YES	AB & DH
GRL	whole unit	YES	AB & DH
JNT	3' long	YES	AB & DH
LTL	progress steps following each detail	YES	AB & DH
MAS	3' high x 4' long	YES	AB & DH
PNT	3' high x 4' long (for each mortar formulation and joint configuration)	YES	AB & DH
RAI	Typical assembly length at roof (see detail RAI 01)	YES	AB
SCR	whole unit	YES	AB & DH
SIL	whole unit	YES	AB & DH
SPN	4' long x height of detail	YES	AB & DH
STN	3' high x 4' long	YES	AB
STR	3' x 3' surface area	YES	DH
TRC	as directed by Architect for repairs whole unit for replacement	YES	AB & DH
	-		


Contractor shall provide Mockup locations to be reviewed by the Director's Representative. See specification section **014339** Mockup Requirements and specification sections listed in the detail list on sheet G-005 for further information. Contractor shall coordinate with the Director's Representative to select which individual Mockups shall be integrated into one "Master" Mockup.

BID A	LTERNATE #2			
ITEM	SPECIFICATION REFERENCE	DETAIL CODE	DESCRIPTION	DWG
Α			CLEANING	
01	040123	CLN 05	CLEANING - TERRA COTTA UNITS SF	A-506
В			MASONRY	
01	040513	PNT 04	REPOINTING TERRA COTTA MORTAR JOINTS LF	A-567
02	042129	TRC 04	TERRA COTTA UNIT REPLACEMENT - DRILL HALL EA	A-585 TO A-587
03	042129	TRC 05	TERRA COTTA CANOPY RECONSTRUCTION SOUTH - (TOP LEVEL)	A-589 TO A-591
04	042129	TRC 06	TERRA COTTA CANOPY RECONSTRUCTION NORTH - (TOP LEVEL)	A-592 TO A-594
С			STEEL REINFORCEMENT	
01	051200	STL 02	STEEL BEAM REINFORCEMENT AT TERRA COTTA CANOPY	A-589

DESIGN & CONSTRUCTION

CONSULTANT

CERTIFICATE OF AUTHORIZATION #: 0006552



14 WALL ST **NEW YORK, NY**

Environmental Sub-consultants: WATTS Architecture & Engineering Estimate Sub-consultants:

Singleton Construction Consultants

PROFESSIONAL'S KNOWLEDGE, BELIEF, AND PROFESSIONAL JUDGEMENT, THE DRAWINGS, BEARING MY PROFESSIONAL SEAL AND SIGNATURE MEET OR EXCEED THE 2020 NEW YORK STATE ENERGY CODE CONSISTING OF THE 2018 INTERNATIONAL ENERGY CONSERVATION CODE, 2016 ASHRAE 90.1.

UNIFORM CODE STATEMENT:
TO THE BEST OF THE REGISTERED DESIGN PROFESSIONAL'S KNOWLEDGE, BELIEF AND PROFESSIONAL JUDGEMENT, THESE PLANS AND/ OR SPECIFICATIONS ARE IN COMPLIANCE WITH THE 2020 UNIFORM CODE.

WARNING:

THE ALTERATION OF THIS MATERIAL IN ANY WAY, UNLESS DONE UNDER THE DIRECTION OF A COMPARABLE PROFESSIONAL, I.E. ARCHITECT FOR AN ARCHITECT, ENGINEER FOR AN ENGINEER OR LANDSCAPE ARCHITECT FOR A LANDSCAPE ARCHITECT, IS A VIOLATION OF THE NEW YORK STATE EDUCATION LAW AND/OR REGULATIONS AND IS A CLASS 'A' MISDEMEANOR.



PROVIDE MASONRY REPAIRS PHASE 2

LOCATION:

STATE ARMORY 2366 5TH AVENUE NEW YORK, NEW YORK

DIVISION OF MILITARY AND NAVAL AFFAIRS

04/16/2024 | ADDENDUM #3 02/27/2024 BID DOCUMENTS DESCRIPTION **47295** – C NUMBER:


APPROVED:

FIELD CHECK:

RESTORATION SUMMARY (cont.)

AB/HB/MZ/MEK/VY/LY/OG

G-006




NEW YORK OF OFFICE OF GENERAL Services

DESIGN & CONSTRUCTION

CONSULTANT

CERTIFICATE OF AUTHORIZATION #: 0006552



14 WALL ST NEW YORK, NY

Environmental Sub-consultants: WATTS Architecture & Engineering
Estimate Sub-consultants:

Singleton Construction Consultants

<u>RGY CODE WRITTEN STATEMENT:</u> THE BEST OF THE REGISTERED DESIG

PROFESSIONAL'S KNOWLEDGE, BELIEF, AND PROFESSIONAL JUDGEMENT, THE DRAWINGS, BEARING MY PROFESSIONAL SEAL AND SIGNATURE MEET OR EXCEED THE 2020 NEW YORK STATE ENERGY CODE CONSISTING OF THE 2018 INTERNATIONAL ENERGY CONSERVATION CODE, 2016 ASHRAE 90.1.

UNIFORM CODE STATEMENT:
TO THE BEST OF THE REGISTERED DESIGN
PROFESSIONAL'S KNOWLEDGE, BELIEF AND PROFESSIONAL
JUDGEMENT. THESE PLANS AND/ OR SPECIFICATIONS
ARE IN COMPLIANCE WITH THE 2020 UNIFORM CODE.

WARNING:

THE ALTERATION OF THIS MATERIAL IN ANY WAY, UNLESS DONE UNDER THE DIRECTION OF A COMPARABLE PROFESSIONAL, I.E. ARCHITECT FOR AN ARCHITECT, ENGINEER FOR AN ENGINEER OR LANDSCAPE ARCHITECT FOR A LANDSCAPE ARCHITECT, IS A VIOLATION OF THE NEW YORK STATE EDUCATION LAW AND/OR REGULATIONS AND IS A CLASS 'A' MISDEMEANOR.



CONSTRUCTION

PROVIDE MASONRY REPAIRS
PHASE 2

LOCATION:

STATE ARMORY 2366 5TH AVENUE NEW YORK, NEW YORK

DIVISION OF MILITARY
AND NAVAL AFFAIRS

3 04/16/2024 ADDENDUM #3
02/27/2024 BID DOCUMENTS

MARK DATE DESCRIPTION

PROJECT NUMBER: 47295 — C

DESIGNED BY: NK/KH

DRAWN BY: AB/HB/MZ/MEK/VY/LY/OG

SHEET TITL

FIELD CHECK:

APPROVED:

RESTORATION ASSEMBLY DETAILS — STN 02A

DRAWING NUMBER:

A - 578

SHEET 115 OF 133

L:\6600s\6659R02 (Fifth Avenue Armory)nck\02 CONTRACT DOCUMENTS\Submissions (pdfs and dwfs)\2024.04.01 Final Bid Documents from OGS\Addendum O3\v

6×24 PLOT SHEET