



Office of General Services

DESIGN & CONSTRUCTION GROUP
THE GOVERNOR NELSON A. ROCKEFELLER
EMPIRE STATE PLAZA
ALBANY, NY 12242

ADDENDUM NO. 1 TO PROJECT NO. 47283

CONSTRUCTION WORK REHABILITATE GORDON DAM HICKOK BROOK MULTIPLE USE AREA TOWN OF HIGHLAND SULLIVAN COUNTY, NY

July 22, 2025

NOTE: This Addendum forms a part of the Contract Documents. Insert it in the Project Manual. Acknowledge receipt of this Addendum in the space provided on the Bid Form.

SPECIFICATIONS

1. SECTION 334613 DRAINS, Paragraph 3.06 A.: Change Paragraph to read:
 - “A. Conform to details shown on Contract Drawings and specified herein; joints watertight at the pressures specified except where unsealed joints are indicated. Joints shall be bell and spigot type with elastomeric gaskets, coupling type, or solvent cement bell and spigot.”

2. SECTION 334613 DRAINS, Article 3.06: Add the following Paragraphs:
 - “C. Position bells upstream. Wipe inside of sockets and outside of pipe to be jointed, clean and dry.

 - D. When a lubricant is required to facilitate joint assembly, it shall be a type having no deleterious effect on the gasket or pipe materials.

 - E. Place reference marks on the spigot ends to assist in determining when proper seating depth has been achieved at the joint.”

END OF ADDENDUM

Brady M. Sherlock, P.E.
Director, Division of Design
Design & Construction